

MOVEABLE SHELVING PROJECT OBSERVATIONS AS OF 7-27-71

- ✓ 1. Bay 1, Sect. 2, Aisle 1 (aisle nearest motor) -- Secondary safety hits shelves before it hits base blocks.
- ✓ 2. Bay 2, Sect. 3 -- Anti-tipping device installed at least 2" from edge of shelves. It should be right on end of shelves except back 1" on end panel end.
3. Bay 1, Sect. 2, Aisle 1 -- lower secondary safety too close to stationary base and needs to be secured to all base blocks.
4. Bay 1, Sect. 1, Aisle 2 -- The bolts need to be turned over into overhead arm extender.
5. Bay 1, Sect. 1 Stationary -- Not room for boxes because of wires. In fact, there is a serious design problem on all equipment and wires on top shelf for all of Bay 1 that will have to be resolved before work continues on next bays:

arm extender placement  
excess wire in way of boxes  
wires over edge of sharp metal

6. Bay 1, Sect. 2 Stationary -- 15" shelf needs end panel.
7. Motor covers do not cover opening completely.
8. Bay 1 & 2, Sect. 2 & 4 -- Mosler alarm boxes hidden behind stationary.
9. Bay 1, Sect. 1 & 2 -- Bolts need tightening in upright bolster plates.
10. Bay 1, Sect. 1 & 2 -- Wire to chain pickup box needs clips and wire to motor for Sect. 3 needs grommet.
11. Center aisle -- Ramp at door not poured.
12. Bay 1, Sect. 1 & 2 -- Shelves and rails will need another cleaning and motor covers installed just prior to turn over to using service.
13. Bay 3, Sect. 6 -- Fire pump conduit needs moving.
14. Bay 2, Sect. 4 -- Fire hose pipe and rack needs work.

25X1A9a

25X1A9a

C/Using Service

25X1A9a

Distribution:

Approved For Release 2001/07/17 : CIA-RDP74-00005R000100080013-2

CIA-RDP74-00005R000100080013-2

1 -

1 -

1 -

1 -